



## **CERTIFICATE OF ANALYSIS**

**Batch No:** 21-47596 920503 Final Report

Client:

Contact: Address

PO No:

Sampler Name:

ALS Program Ref:

Page

Page 1 of 2

Laboratory **Bendigo Laboratory** Address

15 Wellsford Drive. East Bendigo,

VIC 3550 03 5441 0700

Phone Fax

Contact:

Client Manager

Date Sampled: 06-Oct-2021

Date Samples Received: 06-Oct-2021 12-Oct-2021

Date Issued:

Program Description: **CFA VEMTC Program - Huntly** Client Ref: CFA Huntly HU\_TA09

**Not Available** 

SEVERSACFAHUNT

The hash (#) below indicates methods not covered by NATA accreditation in the performance of this service .

					_
Analysis	Method	Laboratory	Analysis	Method	Laboratory
Field Cl2	# EN67.2	Bendigo	DO (Field)	# EN67.2	Bendigo
EC (Field)	# EN67.2	Bendigo	pH (Field)	# EN67.2	Bendigo
Redox (Field)	# EA075FD	Bendigo	Temp (Field)	# EN67.2	Bendigo
BOD5	WP030	Scoresby	Colilert (2000)	MM514	Scoresby
Enterolert	MM517	Scoresby	Ps aeruginosa	MM528	Scoresby
SS at 104+/- 2°C	WA025	Scoresby			

Signatories

Title Title Name Name **Client Manager Team Leader Nutrients Analyst** Chemist **Analyst** 

ac-MR/

NATA Accreditation No. 992 ted for compliance with ISO/IEC 17025 - Testing

The report shall not be reproduced, except in full and results relate only to the items tested

Samples collected by ALS according to procedure EN/67.

Soil microbiological testing was commenced within 4 days from the day collected unless otherwise stated.

Water microbiological testing was commenced on the day received and within 24 hours of sampling unless otherwise stated.

MM524: Plate count results <10 per mL and >300 per mL are deemed as approximate.

MM526: Plate count results <2,500 per mL and >250,000 per mL are deemed as approximate.

Calculated results are based on raw data.

Legionella species refers to Legionella species other than Legionella pneumophila Measurement Uncertainties values for your compliance results are available at this link

Samples are tested within holding time unless otherwise stated.

 Page:
 Page 2 of 2

 Batch No:
 21-47596

 Report Number:
 920503

Client: Senversa Pty Ltd

ALS Program Ref: SEVERSACFAHUNT

Program Description: CFA VEMTC Program - Huntly



Sample No	Site Code	Site Description	Sample Type	Sampled Date/Time
7181379	HU_TA09	Small Tank - NW Corner	WATER	06/10/21 11:30

Analysis - Analyte	Sample No. Site Code Units	7181379 HU_TA09
Temp (Field) - Temperature (Field)	С	14.8
pH (Field) - pH (Field)	Units	7.1
EC (Field) - Electrical Conductivity (Field)	uS/cm	220
DO (Field) - Dissolved Oxygen (Field)	mg/L	8.7
Field Cl2 - Free Chlorine (Field)	mg/L	<0.05
Field Cl2 - Total Chlorine (Field)	mg/L	<0.05
Redox (Field) - Redox Potential (Field)	mV	158.8
BOD5 - Biochemical Oxygen Demand, 5 Day	mg/L	<2
SS at 104+/- 2 C - Suspended Solids	mg/L	<2
Colilert (2000) - E.coli MPN Colilert	orgs/100mL	0
Enterolert - Enterococci MPN Enterolert	orgs/100mL	0
Ps aeruginosa - Pseudomonas aeruginosa	orgs/100mL	0

A blank space indicates no test performed.