



CERTIFICATE OF ANALYSIS

Batch No: 17-10769

Final Report 618113

Laboratory

Page 1 of 2

Address

Page

Scoresby Laboratory Caribbean Business Park.

22 Dalmore Drive.

Scoresby,

VIC 3179

03 8756 8000

Phone 03 9763 1862

Contact:

Fax

Client Manager

Not Available

27-Mar-2017

Sampler Name:

Client:

Contact:

Address:

PO No:

Date Sampled: Date Samples Received:

27-Mar-2017

CFA ALS Program Ref:

31-Mar-2017

Date Issued:

Program Description:

Miscellaneous Analyses

Country Fire Authority

PATTERSON LAKES VIC 3197

PO Box 717

Client Ref:

WQMP

The sample(s) referred to in this report were analysed by the following method(s) under NATA Accreditation No. 992. The hash (#) below

indicates methods not covered by NATA accreditation in the performance of this service .

Analysis Method Analysis Laboratory

Method

Laboratory

Colilert (2000)

MM514

Scoresby

Ps aeruginosa

MM528

Scoresby

Where a result is required to meet compliance limits the associated uncertainty must be considered. Refer to the ALS Contact for details.

Signatories

These results have been electronically signed by the authorised signatories indicated below. Electronic signing has been carried out in compliance with procedures specified in 21 CFR Part 11

Name Title Title Name **Deputy Team Leader**

Analyst

Microbiology

Samples collected by ALS according to procedure EN/67.

Soil results expressed in mg/kg dry weight unless specified otherwise. Soil microbiological testing was commenced within 48 hours from the day received unless otherwise stated. Water microbiological testing was commenced on the

day received and within 24 hours of sampling unless otherwise stated.

MM524: Plate count results <10 per mL and >300 per mL are deemed as approximate.

MM526: Plate count results <2,500 per mL and >250,000 per mL are deemed as approximate.



 Page:
 Page 2 of 2

 Batch No:
 17-10769

 Report Number:
 618113

Client: Country Fire Authority

ALS Program Ref: CFA

Program Description: Miscellaneous Analyses



| Sample No | Site Code | Site Description | Sample Type | Sampled Date/Time |
|-----------|-----------|---------------------|-------------|-------------------|
| 5108366 | CFAB02 | South MegalitreTank | WATER | 27/03/17 13:05 |
| 5108367 | CFAB03 | North MegalitreTank | WATER | 27/03/17 12:50 |

| Analysis - Analyte | Sample No. Site Code Units | 5108366 CFAB02 | 5108367 CFAB03 |
|--|----------------------------------|-------------------|-------------------|
| Colilert (2000) - E.coli MPN Colilert | orgs/100mL | 0 | 0 |
| Ps aeruginosa - Pseudomonas aeruginosa | orgs/100mL | 0 | 0 |

A blank space indicates no test performed.