



CERTIFICATE OF ANALYSIS

Batch No: 18-38017
Final Report
Client: Country Fire Authority
Contact:
Address: PO Box 717
 PATTERSON LAKES VIC 3197

Page **Page 1 of 2**
Laboratory
Address Scoresby Laboratory
 Caribbean Business Park,
 22 Dalmore Drive,
 Scoresby,
 VIC 3179
Phone 03 8756 8000
Fax 03 9763 1862
Contact:
 Client Manager

PO No: 4500376037 V703
Sampler Name:
ALS Program Ref: CFA
Program Description: Miscellaneous Analyses
Client Ref: WQMP - Bangholme

Date Sampled: 24-Sep-2018
Date Samples Received: 24-Sep-2018
Date Issued: 02-Oct-2018

The hash (#) below indicates methods not covered by NATA accreditation in the performance of this service.

Analysis	Method	Laboratory	Analysis	Method	Laboratory
Colilert (2000)	MM514	Scoresby	Ps aeruginosa	MM528	Scoresby

Signatories

Name	Title	Name	Title
	Analyst		

Samples collected by ALS according to procedure EN/67.
 Soil results expressed in mg/kg dry weight unless specified otherwise. Soil microbiological testing was commenced within 48 hours from the day received unless otherwise stated. Water microbiological testing was commenced on the day received and within 24 hours of sampling unless otherwise stated.
 MM524: Plate count results <10 per mL and >300 per mL are deemed as approximate.
 MM526: Plate count results <2,500 per mL and >250,000 per mL are deemed as approximate.
 Calculated results are based on raw data.
 Legionella species refers to Legionella species other than Legionella pneumophila
 Measurement Uncertainties values for your compliance results are available at this link



Sample No	Site Code	Site Description	Sample Type	Sampled Date/Time
5778621	CFAB02	South Megalitre Tank- Tap on tank	WATER	24/09/18 08:50
5778622	CFAB03	North Megalitre Tank- Tap on tank	WATER	24/09/18 08:40

Analysis - Analyte	Sample No. Site Code Units	5778621	5778622
		CFAB02	CFAB03
Colilert (2000) - E.coli MPN Colilert	orgs/100mL	0	0
Ps aeruginosa - Pseudomonas aeruginosa	orgs/100mL	0	0

A blank space indicates no test performed.